

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS NO. DC-775-A

1318 VERMONT AVE., NW, CARRIAGE HOUSE
(MARY McLEOD BETHUNE HOUSE, CARRAIGE HOUSE)
Washington
District of Columbia

HABS
DC
WASH,
589A-

Photographer, Jack E. Boucher, July 1993

DC-775-A-1 VIEW OF EAST ELEVATION OF CARRIAGE HOUSE AND BACK
YARD.